



<b>Tipo</b>	Multimetro analogico
<b>Misura tensione DC</b>	0~2.5/10/50/250/500 V (2k $\Omega$ /V) $\pm$ 0.5% f.s.
<b>Misura tensione AC</b>	0~10/50/500 V (2k $\Omega$ /V) $\pm$ 0.5% f.s.
<b>Misura corrente DC</b>	0~0.5m/10m/250mA $\pm$ 5% f.s.
<b>Misura resistenza</b>	R x 10, R x 1K $\Omega$ $\pm$ 5% f.s.
<b>Misura tensione batteria</b>	1.5V (125mA)/9V (10mA) $\pm$ 10% f.s.