



MULTIMETRI ANALOGICI

Tipo	Multimetro analogico
Misura tensione DC	0~0.1/0.5/2.5/10/50/250/1000 V (20kΩ/V) ±3% f.s.
Misura tensione AC	0~10/50/250/1000 V (9kΩ/V) ±4% f.s.
Misura corrente DC	0~50μ/5m/50m/500m/10A ±3% f.s.
Misura resistenza	R x 1/R x 10/R x 100/R x 1K/R x 10KΩ ±3% f.s.
Cicalino	incluso per indicare continuità

